

2430 "E" Street N. W.
Washington, D. C.
20 October 1953

25X1A9a

Hardware for Door No. 1

25X1A9a

Dear Mr. [REDACTED]:

25X1A9a

The question of hardware for door opening No. 1 was the subject of your letter of 11 August 1953. The subsequent answer by Mr. [REDACTED], dated 28 August 1953, authorized the change from double-acting to single action doors and for adjusting the hardware to suit the change.

It appears that this change was authorized primarily to take care of the hardware problem.

Changing stile width to 3" at this time is undesirable as it would probably involve extra cost and possible delay. Suggest that you discuss this problem with the Contractor and make a recommendation for the most practical solution for doors with 2" stiles.

Very truly yours,

25X1A9a